

Oil Field Environmental Incident Summary

Incident: 20141206103600

Date/Time of Notice: 12/06/2014 10:36

Responsible Party: Liberty Oilfield Services

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: SALEM 4-6H

Field Name: DOLLAR JOE

Well File #: 29037

Date Incident: 12/5/2014

Time Incident: 17:30

Facility ID Number:

County: WILLIAMS

Twp: 155

Rng: 97

Sec: 6

Qtr:

Location Description:

Submitted By: Shane Knuchel

Received By:

Contact Person: Nate Nygard
5018 142nd Avenue NW
Williston, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pump Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	2	Barrels	2	Barrels		

Description of Other Released Contaminant:

Slickwater

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Vac skid and absorbent pads were used to suck up and absorb all standing fluid and effected snow.

Wastes Disposal Location: Oaks Disposal

Agencies Involved: Notified Jim Potts NDIC by phone on 12/4/2014 at 10:20 AM

Updates

Date: 12/7/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a pump leak apparently during fracking activities, remained on location according to the report. NDIC retains oversight.